



Make	MERCEDES-BENZ
Type	SPRINTER 513 CDI
Kind	Van
Specification	Closed Van
Matriculation year	2016
Chassisnumber	WDB9061551N659692
Mileage	134,948 km
Technical condition	★★★★★

Price

€ 25950



More information about this vehicle?

Contact me

Kleyn

+31 183 668 222

info@kleyn.com

Equipment

Chassis

Number of axles	2
Configuration	4x2
Twin tires	✓
Loading Capacity	445 kg
Own weight	3,055 kg
Gross vehicle weight	3,500 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,000 kg
Suspension type	spring suspension

Cabin

Cabin type	single cabin
Airconditioning	✓
Number of airbags	1
Coloured windows	✓
Electric windows	✓
Electric mirrors	✓
Drivers position	Left hand drive
Color	white

Drivetrain

Engine capacity	95 Kw (127 Pk)
Fuel type	diesel
Euro	6
Gearbox kind	Automatic
Power steering	✓
ABS	✓
ASR	✓

Superstructure

Build kind	Extra long - Standard roof
------------	----------------------------

Superstructure

Woodlined box	✓
---------------	---

Chairs

Number of seats	3
Seat cover	cloth

Taillift

Taillift	✓
Tail-lift kind	normal
Tail-lift capacity	750 kg
Tail-lift make	dhollandia dhlm 10
Tail-lift material	aluminium
Tail-lift size	158 x 218
Tail-lift voltage	12

Remarks

514 CDI AC AUTOMAAT!

Tyres/Wheels

Sparewheel	✓
Spare tire profile	4 mm



Azewijnseweg 9
4214 KC Vuren
The Netherlands



P.O. Box 3
4214 ZJ Vuren
The Netherlands



RABO Bank
BIC/SWIFT: RABONL2U
IBAN: NL32RAB00317847430



Kleyn Vans BV
BTW/VAT: NL807901337B01
Kvk/Coc: 11044363

Inspection report

Chassis

Dashboard display codes

Electrical

★★★★★

★★★★★

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

★★★★★

★★★★★

★★★★★

★★★★★

★★★★★

★★★★★

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

★★★★★

★★★★★

★★★★★

★★★★★

🛢️

★★★★★

★★★★★

★★★★★

Superstructure

Internal condition

External condition

★★★★★

★★★★★

Taillift

Controls

System

★★★★★


★★★★★

Tyres/Wheels

Tyres

★★★★★

- ★★★★★★
- ★★★★★
- ★★★★★
- ★★★★
- ★★★
- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements



Tires and axles

