



Make	MERCEDES-BENZ
Type	SPRINTER 319 CDI
Kind	Van
Specification	Closed Van
Matriculation year	2009
Chassisnumber	WDB9066331S395419
Mileage	321,119 km
Technical condition	★★★★★

Price

€ 7950



More information about this vehicle?

Contact me

Kleyn

+31 183 668 222

info@kleyn.com

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	1,200 kg
Own weight	2,000 kg
Gross vehicle weight	3,200 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,000 kg
Towing bracket	✓
Suspension type	spring suspension

Cabin

Cabin type	single cabin
Airconditioning	✓
Number of airbags	1
Parking assistance	Front and back
Coloured windows	✓
Electric windows	✓
Electric mirrors	✓
Partition	✓
GPS navigation	✓
Drivers position	Left hand drive
Color	Silver
Metallic	✓

Drivetrain

Engine make	Mercedes
Engine type	V6
Engine capacity	140 Kw (188 Pk)
Fuel type	diesel
Euro	4

Drivetrain

Gearbox kind	Automatic
Number of Gears	6
Power steering	✓
ABS	✓
ASR	✓

Superstructure

Build kind	Medium length - High roof
Boxmaterial	Plywood
Woodlined box	✓
Rear step	✓
Sidedoors	1
Back doors	Double door

Chairs

Number of seats	3
Seat cover	cloth

Remarks

CDI L2H2 AC NAVI AUTOMAAT 6 CYL 190 PK!

Tyres/Wheels

Sparewheel	✓
Spare tire profile	1 mm



Azewijnseweg 9
4214 KC Vuren
The Netherlands



P.O. Box 3
4214 ZJ Vuren
The Netherlands



RABO Bank
BIC/SWIFT: RABONL2U
IBAN: NL32RAB00317847430



Kleyn Vans BV
BTW/VAT: NL807901337B01
Kvk/Coc: 11044363

Inspection report

Chassis

Dashboard display codes

Electrical

★★★★★

★★★★★

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

★★★★★

★★★★★

★★★★★

★★★★★

★★★★★

★★★★★

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

★★★★★

★★★★★

★★★★★

★★★★★

★★★★★

★★★★★

★★★★★

Superstructure

Superstructure

Internal condition

External condition

★★★★★

★★★★★


★★★★★

Tyres/Wheels

Tyres

★★★★★

- ★★★★★
- ★★★★★
- ★★★★★
- ★★★★★
- ★★★★★
- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements



Tires and axles

