



Make	MERCEDES-BENZ
Type	SPRINTER 318 CDI
Kind	Van
Specification	Closed Van
Matriculation year	2007
Chassisnumber	WDB9066331S155054
Mileage	315,401 km
Technical condition	★★★★★



More information about this vehicle?

Contact me

Kleyn

+31 183 668 222

info@kleyn.com

## Equipment

### Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	1,535 kg
Own weight	1,965 kg
Gross vehicle weight	3,500 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,000 kg
Towing bracket	✓
Suspension type	spring suspension

### Cabin

Cabin type	single cabin
Cruise control	✓
Number of airbags	1
Coloured windows	✓
Electric windows	✓
Electric mirrors	✓
Drivers position	Left hand drive
Color	Silver
Metallic	✓

### Drivetrain

Engine make	Mercedes
Engine type	V6
Engine capacity	135 Kw (181 Pk)
Fuel type	diesel
Euro	4
Gearbox kind	Automatic
Number of Gears	6
Power steering	✓

### Drivetrain

ABS	✓
ASR	✓

### Superstructure

Sidedoors	1
Back doors	Double door

### Chairs

Number of seats	3
Seat cover	cloth

### Tyres/Wheels

Sparewheel	✓
Spare tire profile	7 mm



Azewijnseweg 9  
4214 KC Vuren  
The Netherlands



P.O. Box 3  
4214 ZJ Vuren  
The Netherlands



RABO Bank  
BIC/SWIFT: RABONL2U  
IBAN: NL32RABO0317847430



Kleyn Vans BV  
BTW/VAT: NL807901337B01  
Kvk/Coc: 11044363

Inspection report

Chassis

Dashboard display codes ★★★★★  
Electrical ★★☆☆☆

Cabin

Internal ★★★★★  
External ★★★★★  
Steering column ★★★★★  
Suspension ★★★★★  
Chassis 🚚  
Brakes ★★★★★

Drivetrain

Engine, general ★★☆☆☆  
Cooling system ★★★★★  
Fuel system ★★★★★  
Exhaust system ★★★★★  
Greasing system ★★★★★  
Gearbox ★★★★★  
Clutch ★★★★★  
Drivetrain ★★★★★


Superstructure

Superstructure ★★★★★  
Internal condition ★★★★★  
External condition ★★★★★

Tyres/Wheels

Tyres ★★★★★

- ★★★★★★ Very good state
- ★★★★★ Good state
- ★★★★★ Reasonable state
- ★★★☆☆ Moderate state
- ★☆☆☆☆ Does not meet requirements



Tires and axles

