



Make	MERCEDES-BENZ
Type	SPRINTER 513 CDI
Kind	Van
Specification	Closed Van
Matriculation year	2016
Chassisnumber	WDB9061551N670068
Mileage	136,621 km
Technical condition	★★★★★

Price

€ 25950



More information about this vehicle?

Contact me

Kleyn

+31 183 668 222

info@kleyn.com

## Equipment

### Chassis

Number of axles	2
Configuration	4x2
Twin tires	✓
Loading Capacity	430 kg
Own weight	3,070 kg
Gross vehicle weight	3,500 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,000 kg
Suspension type	spring suspension

### Cabin

Cabin type	single cabin
Airconditioning	✓
Number of airbags	1
Coloured windows	✓
Electric windows	✓
Electric mirrors	✓
Drivers position	Left hand drive
Color	white

### Drivetrain

Engine capacity	95 Kw (127 Pk)
Fuel type	diesel
Euro	6
Gearbox kind	Automatic
Power steering	✓
ABS	✓
ASR	✓

### Superstructure

Build kind	Extra long - Standard roof
------------	----------------------------

### Superstructure

Woodlined box	✓
Sidedoors	1

### Chairs

Number of seats	3
Seat cover	cloth

### Taillift

Taillift	✓
Tail-lift kind	normal
Tail-lift capacity	750 kg
Tail-lift make	dhollandia dhlm 10
Tail-lift material	aluminium
Tail-lift size	158 x 218
Tail-lift voltage	12

### Remarks

514 CDI AC AUTOMAAT!

### Tyres/Wheels

Sparewheel	✓
Spare tire profile	3 mm



Azewijnseweg 9  
4214 KC Vuren  
The Netherlands



P.O. Box 3  
4214 ZJ Vuren  
The Netherlands



RABO Bank  
BIC/SWIFT: RABONL2U  
IBAN: NL32RAB00317847430



Kleyn Vans BV  
BTW/VAT: NL807901337B01  
Kvk/Coc: 11044363

Inspection report

Chassis

- Dashboard display codes
- ★★★★★
- Electrical
- ★★★★★

Cabin

- Internal
- ★★★★★
- External
- ★★★★★
- Steering column
- ★★★★★
- Suspension
- ★★★★★
- Chassis
- ★★★★★
- Brakes
- ★★★★★

Drivetrain

- Engine, general
- ★★★★★
- Cooling system
- ★★★★★
- Fuel system
- ★★★★★
- Exhaust system
- ★★★★★
- Greasing system
- ★★★★★
- Gearbox
- ★★★★★
- Clutch
- ★★★★★
- Drivetrain
- ★★★★★

Superstructure

- Internal condition
- ★★★★★
- External condition
- ★★★★★


Taillift

- Controls
- ★★★★★
- System
- ★★★★★

Tyres/Wheels

- Tyres
- ★★★★★

- ★★★★★★
- Very good state
- ★★★★★
- Good state
- ★★★★★
- Reasonable state
- ★★★☆☆
- Moderate state
- ★★☆☆\*
- Does not meet requirements



Tires and axles

