



Make	MERCEDES-BENZ
Type	SPRINTER 516 CDI
Kind	Van
Specification	Closed Van
Matriculation year	2010
Chassisnumber	WDB9066531S452649
Mileage	279,326 km
Technical condition	★★★★☆

Price

€ 6999



More information about this vehicle?

Contact me

Kleyn

+31 183 668 222

info@kleyn.com

Equipment

Chassis

Number of axles	2
Configuration	4x2
Twin tires	✓
Loading Capacity	1,310 kg
Own weight	2,190 kg
Gross vehicle weight	3,500 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	3,500 kg
Towing bracket	✓
Suspension type	spring suspension

Cabin

Cabin type	single cabin
Cruise control	✓
Tacho	✓
Digital tachograph	✓
Airconditioning	✓
Number of airbags	1
Parking assistance	Back
Electric windows	✓
Electric mirrors	✓
Partition	✓
Drivers position	Left hand drive
Color	Green

Drivetrain

Engine capacity	120 Kw (161 Pk)
Fuel type	diesel
Euro	5
Reinforced engine break	✓

Drivetrain

Gearbox kind	Automatic
Power steering	✓
ABS	✓
ASR	✓

Superstructure

Build kind	Medium length - High roof
Woodlined box	✓
Rear step	✓
Sidedoors	1
Back doors	Double door

Chairs

Number of seats	2
Seat cover	cloth

Tyres/Wheels

Sparewheel	✓
Spare tire profile	1 mm



Azewijnseweg 9
4214 KC Vuren
The Netherlands



P.O. Box 3
4214 ZJ Vuren
The Netherlands



RABO Bank
BIC/SWIFT: RABONL2U
IBAN: NL32RAB00317847430



Kleyn Vans BV
BTW/VAT: NL807901337B01
Kvk/Coc: 11044363

Inspection report

Chassis

Tacho	★★★★★
Dashboard display codes	★★★★☆
Electrical	★★★★☆

Cabin

Internal	★★★★☆
External	★★★★☆
Steering column	★★★★☆
Suspension	★★★★☆
Chassis	★★★★☆
Wheelsuspension	★★★★☆
Brakes	★★★★☆

Drivetrain

Engine, general	★★★★☆
Cooling system	★★★★☆
Fuel system	★★★★☆
Exhaust system	★★★★☆
Greasing system	★★★★☆
Gearbox	★★★★☆
Clutch	★★★★☆
Drivetrain	★★★★☆


Superstructure

Internal condition	★★★★☆
External condition	★★★★☆

Tyres/Wheels

Tyres	★★★★☆
-------	-------

★★★★★★	Very good state
★★★★★	Good state
★★★★☆	Reasonable state
★★★☆☆	Moderate state
★★☆☆*	Does not meet requirements



Tires and axles

