



Make	MERCEDES-BENZ
Type	SPRINTER 311 CDI
Kind	Van
Specification	Closed Van
Matriculation year	2006
Chassisnumber	WDB9036611R787355
Mileage	317,893 km
Technical condition	★★★★★

Price

€ 4950



More information about this vehicle?

Contact me

Kleyn

+31 183 668 222

info@kleyn.com

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	1,670 kg
Own weight	1,830 kg
Gross vehicle weight	3,500 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,000 kg
Towing bracket	✓
Suspension type	spring suspension

Cabin

Cabin type	single cabin
Cruise control	✓
Parking heater	✓
Number of airbags	1
Coloured windows	✓
Electric windows	✓
Partition	✓
Drivers position	Left hand drive
Color	Yellow

Drivetrain

Engine make	Mercedes
Engine capacity	80 Kw (107 Pk)
Fuel type	diesel
Euro	4
Gearbox kind	Manual
Number of Gears	6
Power steering	✓
ABS	✓

Drivetrain

ASR	✓
-----	---

Superstructure

Build kind	Standard length - Standard roof
Woodlined box	✓
Sidedoors	1
Back doors	Double door

Chairs

Number of seats	2
Seat cover	cloth

Remarks

CDI

Tyres/Wheels

Sparewheel	✓
Spare tire profile	2 mm



Azewijnseweg 9
4214 KC Vuren
The Netherlands



P.O. Box 3
4214 ZJ Vuren
The Netherlands



RABO Bank
BIC/SWIFT: RABONL2U
IBAN: NL32RAB00317847430



Kleyn Vans BV
BTW/VAT: NL807901337B01
Kvk/Coc: 11044363

Inspection report

Chassis

Dashboard display codes ★★★★★
Electrical ★★★★★

Cabin

Internal ★★★★★
External  ★★★★★
Steering column ★★★★★
Suspension ★★★★★
Chassis ★★★★★
Brakes ★★★★★

Drivetrain

Engine, general ★★★★★
Cooling system ★★★★★
Fuel system ★★★★★
Exhaust system ★★★★★
Greasing system ★★★★★
Gearbox ★★★★★
Clutch ★★★★★
Drivetrain ★★★★★


Superstructure

Superstructure ★★★★★
Internal condition ★★★★★
External condition ★★★★★

Tyres/Wheels

Tyres ★★★★★

- ★★★★★★ Very good state
- ★★★★★ Good state
- ★★★★★ Reasonable state
- ★★★ Moderate state
- ★ Does not meet requirements



Tires and axles

