



Make	MERCEDES-BENZ
Type	SPRINTER 314 CDI
Kind	Van
Specification	Closed Van
Matriculation year	2018
Chassisnumber	WDB9066331P606259
Mileage	43,403 km
Technical condition	★★★★★

Price

€ 23900



More information about this vehicle?

Contact me

Kleyn

+31 183 668 222

info@kleyn.com

## Equipment

### Chassis

Number of axles	2
Configuration	4x2
Own weight	2,325 kg
Gross vehicle weight	3,500 kg
Suspension type	spring suspension

### Cabin

Cabin type	single cabin
Airconditioning	✓
Number of airbags	1
Electric windows	✓
Electric mirrors	✓
Partition	✓
Drivers position	Left hand drive
Color	white

### Drivetrain

Engine capacity	105 Kw (141 Pk)
Fuel type	diesel
Euro	6
Gearbox kind	Automatic
Power steering	✓
ABS	✓
ASR	✓

### Superstructure

Build kind	Medium length - High roof
Sidedoors	1
Back doors	Double door

### Chairs

Number of seats	3
-----------------	---

### Chairs

Seat cover	cloth
------------	-------

### Remarks

3.5T Trekhaak voorbereiding Automaat Airco

### Tyres/Wheels

Sparewheel	✓
Spare tire profile	8 mm



Azewijnseweg 9  
4214 KC Vuren  
The Netherlands



P.O. Box 3  
4214 ZJ Vuren  
The Netherlands



RABO Bank  
BIC/SWIFT: RABONL2U  
IBAN: NL32RAB00317847430



Kleyn Vans BV  
BTW/VAT: NL807901337B01  
Kvk/Coc: 11044363

Inspection report

Chassis

Dashboard display codes

Electrical

★★★★★

★★★★★

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

★★★★★

★★★★★

★★★★★

★★★★★

★★★★★

★★★★★

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

★★★★★

★★★★★

★★★★★

★★★★★

★★★★★

★★★★★

★★★★★

Superstructure

Internal condition

External condition

★★★☆☆


★★★★☆

Tyres/Wheels

Tyres

★★★★☆

- ★★★★★★
- ★★★★★
- ★★★★☆
- ★★★☆☆
- ★★☆☆\*
- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements



Tires and axles

